




2018 Suzuki Wagon R





CAR INSPECTION REPORT




Car Details

Customer / Dealer Name Ahmed Arslan	Engine Capacity 998 cc	Milage 72375 km	Fuel Type Petrol
Inspection Date 21 Oct, 2024	Chassis No 10057200	Engine No 157288	Registration No LEE - 9945
Location Revenue Society, Lahore	Registered City Lahore	Transmission Type Manual	Color Grey

Summary	Over all Rating: 7.5/10
ENGINE / TRANSMISSION / CLUTCH 94% 	BRAKES 100%
SUSPENSION / STEERING 80% 	INTERIOR 90%

AC / HEATER <p style="text-align: right;">90%</p> 	ELECTRICAL & ELECTRONICS <p style="text-align: right;">100%</p> 
EXTERIOR & BODY <p style="text-align: right;">75%</p> 	TYRES <p style="text-align: right;">50%</p> 

Exterior Condition



Legend

T : Original Piece

P: Paint

A2: Minor Multiple Scratches

E2: Minor Multiple Dents

W: Dry Dent

A1: Minor Scratch

E1: Minor Dent

Note : Bumpers paint and front bumpers grill broken

Body Frame Accident Checklist		100%
Radiator Core Support	ok	
Right Strut Tower Apron	ok	
Left Strut Apron	ok	
Right Front Rail	ok	
Left Front Rail	ok	
Right A Pillar	ok	
Left A Pillar	ok	
Right B Pillar	ok	
Left B Pillar	ok	
Right C Pillar	ok	
Left C Pillar	ok	
Boot Floor	ok	
Boot Lock Pillar	ok	
Rear Sub Frame	ok	
Front Sub Frame	ok	

Engine / Transmission / Clutch

Fluids / Filters Check	
Engine Oil Level	ok
Engine Oil Leakage	ok
Transmission Oil Leakage	ok
Coolant Leakage	ok
Brake Oil Leakage	ok

Exhaust Check	
Exhaust Sound	ok

Engine Cooling System	
Radiator	ok
Suction Fan	ok

Mechanical Check	
Belts (AC)	ok
Belts (Fan) ①	Noisy
Wires (Wiring Harness)	ok
Engine Blow (Manual Check)	ok
Engine Noise	ok
Engine Vibration	ok
Cold Start	ok
Engine Mounts	ok
Pulleys (Adjuster)	ok
Hoses	ok

Transmission check / power train

Engine Electronics	
Starter Operation	ok

Brakes 100%

Mechanical Check	
Front Right Disc	Good
Front Left Disc	Good
Front Right Brake Pad	Good
Front Left Brake Pad	Good
Parking / Hand Brake	Good

Suspension/Steering	80%
---------------------	-----

Front Suspension	
Steering Wheel Play	ok
Right Ball Joint	ok
Left Ball Joint	ok
Right Z Links Boot ❶	Damage
Left Z Links Boot ❶	Damage
Right Tie Rod End	ok
Left Tie Rod End	ok
Front Right Boots ❶	Damage
Front Left Boots ❶	Damage
Front Right Bushes	ok

Front suspension	
Front Left Bushes	ok
Front Right Shock	ok
Front Left Shock	ok
Rear Suspension	
Rear Light Bushes	ok
Rear Left Bushes	ok
Rear Right Shock	ok
Rear Left Shock	ok

Dash / Roof Controls	
Interior Lightings	Ok
Dash Controls - A/C	Ok
Dash Controls – De-Fog	Ok
Dash Controls – Hazard Lights	Ok
Audio / Video ❶	Audio
Rear View Camera	NA
Trunk Release Lever / Button	Ok
Fuel Cap Release Lever/Button	Ok
Bonnet Release Lever/Button	Ok
Polish	
Roof Polish	Ok
Floor Mat	Ok
Front Right Seat Polish	Ok

Rear Seat Polish	Ok
Dashboard Condition	Ok
Equipment	
Spare Tire	Ok
Tools	Ok
Jack	Ok

Steering Controls	
Steering wheel Condition	Ok
Horn	Ok
Lights Lever/Switch(High/Low Beams, Indicator)	Ok
Wiper/Washer Lever(Washer, Speeds)	Ok
Mirrors	
Right Side Mirror	Ok
Left Side Mirror	Ok
Rear View Mirror Dimmer	Ok
Seats	
Right Seat Adjuster Recliner	Ok
Left Seat Adjuster Recliner	Ok
Right Seat Adjuster Lear Track	Ok
Left Seat Adjuster Lear Track	Ok
Right Seat Belt	Ok
Left Seat Belt	Ok
Rear Seat Belts	Ok
Glove Box	Ok
Power/Manual Windows & Central Locking	
Front Right Power Window/Manual Lever	Ok
Front Left Power Window/Manual Lever	Ok
Rear Right Power Window/Manual Lever ¹	Manual

Rear Left Power Window/Manual Lever ❶	Manual
Auto Lock Button	Ok
Window Safety Lock	Ok

AC/Heater 90%

AC / Heater Check Up	
AC Fitted	Ok
AC Operational	Ok
Blower	Noisy

Cooling	Ok
Heating	Ok

Electrical & Electronics 100%

Computer Check Up	
Computer Check up/Malfunction Check	Ok
Battery Warning Light	Ok
Oil Pressure Low Warning Light	Ok
Temperature warning Light/Gauge	Ok
Power Steering Warning Light	Ok
ABS Warning Light	NO
Key Fob Battery Low Light	Ok

Battery	
Voltage	Ok
Terminals Condition	Ok
Charging	Ok
Alternator Operation	Ok
Instrument Cluster	
Gauges	Ok

Exterior & Body 75%

Car Frame	
Trunk Lock	Ok
Front Windshield Condition	Ok
Rear Windshield Condition	Ok
Front Right Door Window	Ok
Front Left Door Window	Ok
Rear Right Door Window	Ok
Rear Left Door Window	Ok
Windscreen Wiper	Ok

Exterior Lights		
Right Headlight (Working) ❶		Scratches
Left Headlight (Working) ❶		Scratches
Right Headlight (Condition)		Ok
Left Headlight (Condition)		Ok
Right Taillight (Working)		Ok
Left Taillight (Working)		Ok
Right Taillight (Condition) ❶		Repair

Left Taillight (Condition)	Broken ❶
Fog Lights (Working)	Ok

Tyres	50%
--------------	------------

Tyres	
Front Right Tyre ❶	50%
Front Left Tyre ❶	50%
Rear Right Tyre ❶	50%
Rear Left Tyre Brand	Euro
Rear Left Tyre ❶	50%
Tyre Size	
Rims	Alloy
Wheel Caps	NO

Test Drive	
Engine Pick	Ok
Clutch Operation (While Driving)	Ok
Gear Shifting (Manual)	Ok
Drive Shaft Noise	Ok
Brake Pedal Operation	Ok
ABS Operation	NO
Front Suspension (While Driving)	Ok
Rear Suspension (While Driving)	Ok
Steering Operation (While Driving)	Ok
Steering Wheel Alignment (While Driving)	Ok
AC Operation (While Driving)	Ok
Heater Operation (While Driving)	Ok
Speedometer (While Driving)	Ok
Test Drive Done By	90%